

OWNER'S BULLETIN

1966 AIRSTREAM 22' - 30' INCLUSIVE
INTERNATIONAL AND LAND YACHT SERIES

SUBURBAN EVERFLO OR NOVENT HEATER

- A. When service requires removing heater from its jacket MAKE SURE:
1. The asbestos gasket around the end of the exhaust tube is replaced if it will no longer provide a seal with the outside cover.
 2. The exhaust tube enters the opening for it in the outside cover when the heater is reassembled. This can be checked by looking in the exhaust vent opening on the outside of the trailer.
- B. Valve to stop gas flow to heater is under the trailer beneath the heater.

IWS/ 9-7-65