

AIRSTREAM

JACKSON CENTER, OHIO 45334 • TELEPHONE (AREA CODE 513) 596-6111


September 25, 1970

Dear John:

We have found a problem on some of the 1971 models, relative to the accessibility of the refrigerator burner and flint lighter. Please examine the units you now have. The problem in servicing the refrigerator will be found only on the M-60 (6 cu.ft.) refrigerators in 23-footers and longer trailers.


It is necessary to have these corrected before they are released to the retail purchaser. I will send you the instructions as to how the corrections are to be made just as quickly as they are available. The important thing is to have them corrected before they are sold.

Very truly,



Carroll Allen
Service Manager
AIRSTREAM, INC.

CA/ew



WALLY BYAM

WESTERN FACTORY: CERRITOS, CALIFORNIA