

AIRSTREAM SERVICE BULLETIN # 140

NEWMARK - TRIAD UNIVOLT EXCHANGE

In addition to the Newmark Univolt Warranty, as outlined in Airstream Service Bulletin 110A, we will offer the following.

Upon expiration of the original warranty period a customer may elect to have a malfunctioning Newmark Univolt re-built according to the charges outlined in Airstream Bulletin 110A, or trade in his Newmark Univolt (1969, 1970 or 1971) at a value of \$75.00 towards the full retail price of the Triad/Utrad Univolt V, model TU345A. The dealer allowance, when trading in the same Newmark Univolt, will be \$40.00 towards the dealer wholesale price of the Triad/Utrad Univolt V. The labor of exchange would be a customer obligation. This offer is made available for a period not to exceed twelve (12) months beyond the original warranty period.

Should a customer elect to take advantage of this offer while still within his two year warranty period Airstream will pay for the labor of exchange.

Attached are two drawings, one to show the installation in 1969 Airstreams, the second showing installation in 1970 and 1971 Airstreams. PLEASE NOTE that the 1970 and 1971 print shows a change that must be made in the control panel.

A TWO YEAR WARRANTY IS GIVEN WITH THE NEW TRIAD/UTRAD UNIVOLT V STARTING AT DATE OF EXCHANGE, WHICH MUST BE VERIFIED BY THE CUSTOMER'S WORK ORDER RECEIPT.

October 15, 1971

DEV/fb