

Airstream Service Tips

SEWAGE DRAIN LINE COVER CAP

With the 1961 models, Airstream introduced a new style sewage drop-out, which incorporates a cover cap for the drain line. This item is required under the MHMA Travel Trailer Standards to prevent the inadvertent discharge of sewage (either from the tank or from the basin drains) when not hooked to a hose.

It has come to our attention, though, that a great number of customers do not remember to remove this cap.....or, as it is called, the "frying pan".....before dumping the septic tank with the result that they have a back-up of sewage in their system.

PLEASE MAKE THIS AN IMPORTANT POINT ON YOUR CUSTOMER CHECK OUT PROCEDURE.

SP-25
3-20-61

